


Silver Lake Sediment Cap Design
In-lake portion: no geotextile or armor stone

NOTE: cap performance std of 0.5% TOC measured in place



Near-shore cap design differs from in-lake design

**NOTE: RCM added as needed during construction along the shore only
when NAPL/sheens were observed**

Monitoring Locations for Sediment Cores

★ - cap monitoring locations

Silver Lake

N
↑

Silver Lake Cap Thickness

2013; 2014; 2015; 2016

